

Mine Name: Duchesne Co/Cedar Buttes 1

Inspector(s): L Heppler

9. Revegetation

Operator Name: Duchesne County Road Department

## **State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining**

MICHAEL R. STYLER Executive Director

JOHN R. BAZA
Division Director

## Inspection Report Minerals Regulatory Program

Date: March 11, 2009

	WWW
Reviewed:	(1/1)
	V

Permit Number: M/047/0028

Inspection Date: 09-17-2008

Time: 5:00 PM

	1 III C. 5.00 1 IVI		
Other Participants: none	Mine Status: ACT		
<b>Elements of Inspection</b>	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	$\bowtie$		
2. Public Safety (shafts, adits, trash, signs, highwalls)	$\overline{\square}$		
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,			
8. Soils	$\overline{\boxtimes}$	$\Box$	

Bond Renewal Date: 12-15-2005 Bond Amount: \$89,800 Permit fee \$500 due - invoice sent out 06/20/2009

Purpose of Inspection: Routine annual Inspection. Last Inspection 08/14/2003

**Inspection Summary:** Highwall is over steepened. No concurrent reclamation has been started. Area has been recently active. Photos were taken to document site conditions.

**Conclusions and Recommendations:** Bond amount needs to be escalated. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: Duchesne County Road Department

O:\M047-Uintah\M0470028-DuchesneCo-Road\inspections\insp-09172008.doc

